Qty:

Each

: STEP WELDMENT

: D2563

: N/A

: C

: D2563 REV C

: 28/05/2009

User:

Monday, 11/05/2009 1:20:32 PM

Julie Dawson

Process Sheet

Drawing Name

Part Number

Material

Due Date

Description:

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 47834A

Estimate Number

: 10176

P.O. Number

This lesue

: 11/05/2009 S.O. No. :

: NC Prsht Rev.

First Issue Previous Run : 11

: 47744A

Written By

Checked & Approved By Comment

: Est Rev:G 02.07.31

Type

Re-format Location RF

: LARGE FAB ASSY

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

Step Extrusion

1.0

D2244116

Comment: Qty.:

1.0000 Each(s)/Unit Total:

10.0000 Each(s)

Pick:

D2244

Step Extrusion

Batch: 0 38

2.0

End Plate

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

20.0000 Each(s)

Pick:

Qty Part No.

Description End Cap

D2673-34

3.0

D2561

Lug

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

20.0000 Each(s)

Pick:

Qty Part No.

Description Lug Plate

Batch

2 D2561

347177

4.0

D2564

Mounting Angle

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

20.0000 Each(s)

Pick:

Qty Part No.

Description

Batch

D2564

Mounting Angle

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO		Ву	Date 0	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
	*		l	e .									
		-											
Part No		PAR #:											
	R			Disposition: QA: N/C Closed: Date					_ Date: _				
NCR:		V	VORK ORD	ER NON-CONF	ORMANCE	(NCR)	8	î				
DATE	STEP	Description of NC		Corrective Action Section B			Verification		Approval	Approval			
DATE	SIEP	Section A	Initial Chief Eng	Action Descri Chief Eng	ption	Sign & Date	Section (Chief Eng	QC Inspector			
										1.			
\$		17			8		÷						
									,				

Date: Monday, 11/05/2009 1:20:33 PM Julie Dawson User: **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 47834A Part Number: D2563 Job Number: Seq. #: Machine Or Operation: Description: LARGE FABRICATION RESOURCE 1 5.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2244 to 89.70" at 34 deg as per dwg D2563 2-Deburr ends 3-Weld (1 END CAP, LUG PLATES & MOUNTING ANGLE) as per dwg D2563 using DT 8343 A/R AL ROD Batch: M//0/30 M//0972 4- Grind VISUAL WELDING INSPECTION 6.0 QC9 Comment: VISUAL WELDING INSPECTION · 010:02 INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING HAND FINISHING RESOURCE #1 8.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 9.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSIO Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION LARGE FAB 1 LARGE FABRICATION RESOURCE 1 10.0 Comment: LARGE FABRICATION RESOURCE 1 Ph 09.06.036 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg D2563 using DT 8343 Batch: M110130 A/R AL ROD 3-Grind


Dart Aerospace	Ltd
----------------	-----

W/O:			W	ORK ORDER CI	HANGES					
DATE	STEP	PRO		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							il			
							5			
							Gel.			
Part No	:	PAR #:	Fault Cate	egory:	NC	R: Yes	No DQ	A:	Date:	
						QA: N/C Closed:				
NCR:		13	WORK ORE	DER NON-CONF	ORMANCE	(NCI	R)	j _a		
DATE	STEP	Description of NC	Corrective Action		Section B			cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Descr Chief Eng	iption	Sign Date		ion C	Chief Eng	QC Inspector
										1 34
										*

Date: Monday, 11/05/2009 1:20:33 PM Julie Dawson User: **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 47834A Part Number: D2563 Job Number: Seq. #: Machine Or Operation: Description: VISUAL WELDING INSPECTION 11.0 QC9 Comment: VISUAL WELDING INSPECTION 12.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 13.0 POWDER COATING Comment: POWDER COATING Touch up Alodine then Powder Coat White Gloss (Ref. 4.3.5.1) as per QSI 005 4.3 m 111472 START TIME: OVEN TEMPERATURE: 3200 FL 09/06/03 FINISH TIME: 14.0 HAND FINISHING RESOURCE #1 m/11/013 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D2563 and QSI 005 4.4 15.0 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPEC POWDER COAT/CHEMICAL CONVERSION FINAL INSPECTION/W/O RELEASE 16.0 Comment: FINAL IN TION/W/O RELEASE Job Completion

Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:		,	WC	RK ORDER C	HANGES					
DATE	STEP	PR		Ву	Date (Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									1	16
										ATTEN TO
		~			÷					
Part No	:	PAR #:	Fault Cate	gory:	N	CR: Yes 1	No DQA:	7	Date:	
		esolution:		QA: N/C Closed:				J. 1946		
NCR:		a ·	WORK ORDE	R NON-CON	ORMANO	E (NCR)				
DATE		Description of NC Section A	Corrective Action Section				Varification			Annuaval
	STEP		Initial Chief Eng	Action Desc Chief En	ription	Sign & Date	Verification Section C		Approval Chief Eng	Approval QC Inspector
									_	
									-1	
										- 11
									6	100



Dart Aerospace L	ta
------------------	----

	•									
W/O:		1		W	ORK ORDER	HANGES	ì			
DATE	STEP		PRO	CEDURE CH	ANGE	P	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			4			8			. ros mg	
										_
		a		=						
		*		1112			g.			
Part No	7 =		PAR #:	Fault Cat	egory:	1	NCR: Yes	No DQA:	_ Date: _	
Resolution:			Dispositi	on:	(QA: N/C Closed: Date			te:	
NCR:			V	VORK ORE	DER NON-CON	FORMAN	CE (NCR)		40
DATE	STEP	Description of NC Section A			Corrective Action Sec			Verification	Approval Chief Eng	Approval QC Inspector
DATE	OTE			Chief Eng	Initial Action Descri Chief Eng Chief Eng		Sign & Date	Section C		
		1	$\chi_{i,j} \in$	1 1						
					1				-	
							, -			3
								5-74		
					- = -					
								1	£	. 3